

## Senzor temperature tip K (NiCrNi)

---

### PAN FLÄCHENFÜHLER without adapter

Senzor područja temperature, K termoelement -50° - +500°C

Senzor područja temperature, K-termopar -50° - +500°C

